## Section C Clayville Industrial – Water infrastructure assessment





## 5. Main Road (Service Road):

Excavation left open and infrastructure exposed – No warning signs or any safety measures in place.



## Excavation material left after the installation of the water pipeline.



## Excavation material left after the installation of the water pipeline which also resulted in damage to the storm water pipeline.

