



Annexure 3.3

April 2026

Clayville Industrial Sidewalks & Road Shoulders assessment report:

No:	STREET NAME / LOCATION:	PHOTOS:	COMMENTS:
1.	Axle Drive:		
1.1			Road shoulder maintenance required.

1.2			Road shoulder cleaning and maintenance required.
1.3			Road surface cleaning required.
2.	Industry Road:		
2.1			Road reinstatement.

2.2				In front of Festive Chickens. Road shoulder maintenance required.
2.3		  		Road shoulder maintenance required.
2.4				Closing of deep excavation required.

2.5				Road shoulder maintenance required.
3.	Spanner Road:			
3.1				31 Spanner Road. Road surface cleaning required.
3.2				Closest intersection Nail Road. Sidewalk maintenance required.

3.3				Clearing required.
3.4				Cleaning and clearing required.
3.5				c/o Southview Road.. Road surface cleaning required.

3.6				Sidewalk maintenance required.
4.	Spanner Road (Upper):			
4.1				Opposite SPAR DC. Road shoulder maintenance required.
4.2				Opposite SPAR DC. Road shoulder maintenance required.

4.3				Opposite SPAR DC. Road shoulder maintenance required.
4.4				Opposite SPAR DC. Road shoulder maintenance required.
4.5				Opposite SPAR DC. Road shoulder maintenance required.

4.6				Intersection Nail Road. Road markings and maintenance required.
4.7				Road surface cleaning required.
4.8		  		c/o Baksteen Road. Reinstatement and maintenance of safety barrier required.

Olifantsfontein Business Forum (OBF) Reg. No. 1992/003378/08
Incorporated as a Non-Profit Company in terms of the Companies Act, Act 71 of 2008 since June 1992.

Domicilium:

Ground Floor, Celtis House
Block D, Eastwood Office Park
Lynwood Road, Lynwood Ridge, Pretoria
Willie van Rooyen Cell: 083 393 4656

Email: manager@olifantsfonteinbusinessforum.co.za
www.olifantsfonteinbusinessforum.co.za