



February 2026

Report to The City of Ekurhuleni

Infrastructure Maintenance & Service Request
for
Clayville Industrial

Pothole assessment report:

No:	STREET NAME:	PHOTOS:	COMMENTS:
1.	Axle Drive:		
1.1			Clover entrance at 25 Axle Drive.
2.	Baksteen Road:		
2.1			In front of 9 Baksteen Road.
3.	Bank Patricia Street		

3.1			Entrance Mega Packaging.
3.3			In front of Shell Garage and Police Station. Reinstatement of road required after repair of a burst water pipe.
3.4			At Shell Garage.
4.	Boron Road:		

4.1				Road maintenace required.
5.	Hammer Road:			
5.1				
6.	Long Avenue:			

6.1				
7.	Nail Avenue:			
7.1		  		
8.	Nut Road:			

8.1			Intersection of Nut & Industry Road.
8.2			Near Dairymaid entrance.
8.3			Road surface maintenance required.
9.	Park Street:		

9.1				
10.	Pebble Lane:			
10.1				Entrance to 151 Pebble Lane
11.	Porceiain Road:			

11.1				
11.2				
12.	Purlin Street North (21 Industrial Estate:)			

12.1				Entrance to Ardagh Glass packaging.
13.	Southview Road:			
13.1				
13.2				Intersection Axle Drive.

14.	Spanner Road:		
14.1			In front of Mapula Nyama Rama.
14.2			In front of Asimbambani.
14.3			Opposite SPAR DC.

14.4			At the collapsed portion of the water canal.
14.5			Road surface reinstatement required.
15.	Spanner Road (Upper):		
15.1			Opposite SPAR DC entrance.

15.2				Near Clover factory shop.
16.	Townhouse Street:			
16.1				Entrance to Clayville East (Glenton Avenue). Road clearing and maintenance required.
16.2				Closest intersection – Boron Road.

16.3				Intersection Porcelain Road. Road surface cleaning required.
------	--	---	--	--

Olifantsfontein Business Forum (OBF) Reg. No. 1992/003378/08
 Incorporated as a Non-Profit Company in terms of the Companies Act, Act 71 of 2008 since June 1992.
 Domicilium:
 Ground Floor, Celtis House
 Block D, Eastwood Office Park
 Lynwood Road, Lynwood Ridge, Pretoria
 Willie van Rooyen Cell: 083 393 4656
 Email: manager@olifantsfonteinbusinessforum.co.za
www.olifantsfonteinbusinessforum.co.za